

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	1	85									
2	NLG	3	110									
3	MDK	6	81									
4	RR(S)	10	102		1		1		1			
5	RR(N)	45	271		1		1		1			
6	RR(E)	33	203									
7	Hyd	135	837		2		2		2			
	Total	233	1689	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	78	891	2		2		2				
2	NLG	109	738		4		4		4			
3	MDK	79	690		3		3		3			
4	RR(S)	31	341									
5	RR(N)	8	48									
6	RR(E)	15	78									
	Total	320	2786	2	7	2	7	2	7	0	0	
	Grand Total	553	4475	2	11	2	11	2	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 25.07.2016

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Chinnamaroor	33KV	Wanaparthi	02.00	07.45	05.45	E/L	Jumpers open at Thirumalipally	Chinnamaroor,Ayyav aripally, Remaddula,Kodair,R ajapur	-
2		Gadwal	Oil Seeds	33KV	Gadwal	16.25	20.30	04.05	E/L	Flash Over Disc Failed Near Veerapur SS	Veerapur,Beechupall y,Kodandapur	-

TSSPDCL - LMRC / Corporate office

Date: 25.07.2016

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Ch Laxmapur	Ch.laxamapur	11KV	Bhongir	07.00	08.40	01.40	E/L	11Kv Line snapped at Ch.laxmapur	-
2		Mothkur	Anajipur	11KV	Bhongir	02.00	06.10	04.10	E/L	11Kv Disk failed ss-1B/d	-
3		Addagudur	Addaguduru	11KV	Bhongir	23.00	02.00	03.00	E/L	B/d HG Fuse Indulasotor Failed	-
4		Keethavarigudem	Rainigudem	11KV	Huzurnagar	05.30	08.20	02.50	E/L	11 kv line snapped at Rainigudem village	-
1	MDK	Thogita	H. Ghanpur	11KV	Medak	11.40	16.00	04.20		B/D Due to 11KV insulator failed & Conductor snapped	-
2		Wadi	Kothapally	11KV	Medak	02.00	08.45	06.45		B/D Due to 11KV Disc failed	-
3		Nasthipur	Kasala	11KV	Medak	21.30	08.30	11.00		B/D Due to 11KV AB Switch insulator failed	-
1	RR S	Kattedan	Gangothri	11KV	RJNR	17.40	19.00	01.20	EL	Breaker Mechanical Problem in sub Station	-
1	RR N	Mayurinagar	Prashanthnagar	11KV	KKP	02.55	04.12	01.17	BD	11kv AB Cable failure opp Indiramma houses at SBI Homes	-
1	HYD N	Clock Tower	Anjali	11KV	V	01.25	03.00	01.35	EL	Sparking AB Switch at Anjali Theater	-----
2		H.P.S	Begumpet Nala	11KV	IV	10.08	13.10	03.02	EL	Cable fault at Begumpet (2Nos DTR's kept off)	Arranged B/F on 11KV Mothilal Nagar feeder