

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	1	85									
2	NLG	3	110									
3	MDK	6	81									
4	RR(S)	10	102		1		1		1			
5	RR(N)	45	271		1		1		1			
6	RR(E)	33	203									
7	Hyd	135	837		4		4		4			
	<b>Total</b>	<b>233</b>	<b>1689</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	78	891	2		2		2				
2	NLG	109	738		4		4		4			
3	MDK	79	690		1		1		1			
4	RR(S)	31	341									
5	RR(N)	8	48									
6	RR(E)	15	78									
	<b>Total</b>	<b>320</b>	<b>2786</b>	<b>2</b>	<b>5</b>	<b>2</b>	<b>5</b>	<b>2</b>	<b>5</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>553</b>	<b>4475</b>	<b>2</b>	<b>11</b>	<b>2</b>	<b>11</b>	<b>2</b>	<b>11</b>	<b>0</b>	<b>0</b>	

## TSSPDCL - LMRC / Corporate office

Date: 06.06.2016

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Paspula Rural Feeder	33KV	Mahabubnagar	17.45	20.30	02.45	E/L&O/L	Pin Banding Replasmnt near Karne Village	Paspula,Mushtipally	-
2		Shadnagar	Salasar Industrial Feeder	33KV	Jadcherla	16.40	20.50	04.10	E/L	Replasmnt of Failure Insulator and Disc near Dava Sree Company	Salasar Industrial	-

TSSPDCL - LMRC / Corporate office

Date: 06.06.2016

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Disincherla	Somaram	11KV	Huzurnagar	15.00	17.00	02.00	EI	Insulator failure	-
2		Sh.Gowraram	Sh.Gowraram	11KV	Suryapet	13.15	15.20	02.05	EL	Insulator failed	-
3		Koppole	Aregudem	11KV	Devarakonda	09.00	11.00	02.00	EL	Jumper cut	-
4		Pajjur	Pajjur	11KV	Nalgonda	07.00	09.30	02.30	EL	HT/LT Lines Melt at Pajjur	-
1	MDK	Chippalthurthy	Jakkapally	11KV	Medak	10.30	15.00	04.30		B/D Due to Conductor snapped at jakkapally village	-
1	RR S	Puppallaguda	Alkapur	11KV	RJNR	05.10	06.12	01.02	B/D	11KV line touching to 33KV Tower pole at Alkapur X Road	-
1	RR N	Papi Reddy Nagar	Papi Reddy Nagar	11KV	GCB	11.50	12.55	01.05	BD	HT/LT Line Phase to Phase Near Shoting Bilding at CM Tota Back Side Papi Reddy Nagar	-
1	HYD N	H.P.S	R.B.I Quarters	11KV	IV	00.37	02.30	01.53	EL,OL-R&Bph	Cable fault	Arranged B/F on 11KV Begumpet Nala feeder
2		R.P Nilayam	Alwal	11KV	VI	06.25	08.05	01.40	EL,OL-Rph	HT Jumper cut at Nava Kala Kendram	-----
3		Gymkhana	Pared Ground	11KV	V	11.45	13.10	01.25	EL	Tree branches & Bird fault on lines at Pared Ground	-----
1	HYD C	Vittalwadi	Taj Mahal	11KV	I	20.30	21.40	01.10	EL	HG fuse blown at Irland Restaurent	-----