

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	52	153									
2	NLG	12	397									
3	MDK	83	350									
4	RR(S)	40	201									
5	RR(N)	74	396									
6	RR(E)	41	337									
7	Hyd	163	965		2		2		2			
	Total	465	2799	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	81	891									
2	NLG	120	738		7		7		7			
3	MDK	81	695	1	2	1	2	1	2			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	15	79									
	Total	336	2789	1	9	1	9	1	9	0	0	
	Grand Total	801	5588	1	11	1	11	1	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 09.11.2016

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Thukkapur	Lingapur	33KV	Siddipet	07.45	09.45	02.00		B/D due to Insulator failed		-

TSSPDCL - LMRC / Corporate office

Date: 09.11.2016

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	S.V Collage	Layola Express	11KV	Suryapet	07.30	08.45	01.15	EL	Bird died on the line	-
2		Kothapally	Peddamunigala	11KV	Devarakonda	03.00	06.00	03.00	EL	Insulator failed	-
3		Pajjur	Pajjur	11KV	Nalgonda	03.00	06.00	03.00	EL	Jumper cut	-
4		Narkatpally IE	Vanipakala	11KV	Nalgonda	07.00	11.00	04.00	EL	Jumper cut	-
5		Repala	Narashimulagudem	11KV	Huzurnagar	07.00	08.00	01.00	EL	Due to 11Kv snapped at Narashimulagudem village	-
6		Thogarai	Kuchipudi	11KV	Huzurnagar	16.40	17.55	01.15	EL	Due to Jumper cut at Kuchipudi Village	-
7		Anathram	Hanumapur	11KV	Bhongir	06.00	10.10	04.10	EL	Jumper cut	-
1	MDK	Malkapur	Mallepally	11KV	Sangareddy	07.10	09.45	02.35		B/D Due to conductor snapped at Gunthapally	-
2		Cheryal	Kalivemula	11KV	Sangareddy	13.00	14.00	01.00		B/D Due to pole damage at Kalivemula Vg	-
1	HYD N	Macha Bollaram	Reddy Enclave	11KV	Bowenpally	12.05	13.10	01.05	EL,OL	Breaker fault at SS, Cable fault & Jumper cut at Alwal	-
2	HYD S	Moosaram Bagh	Sripuram Colony	11KV	Asmangadh	13.30	14.45	01.15	EL,OL-Yph	Faulty 11KV Plant Production feeder loads	-