

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		1		1		1			
5	RR(N)	82	407	1	8	1	8	1	8			
6	RR(E)	38	360		4		4		4			
7	Hyd	186	1014		7		7		7			
	Total	504	2929	1	20	1	20	1	20	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	3	1	3	1	3	1			
2	NLG	150	948		4		4		4			
3	MDK	87	828	2	7	2	7	2	7			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	5	12	5	12	5	12	0	0	
	Grand Total	908	6149	6	32	6	32	6	32	0	0	

TSSPDCL - LMRC / Corporate office

Date: 22.06.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Machanpally	33KV	Mahabubnagar	20.10	21.10	01.00	E/L	Break Down due to Heavy Rain & Wind and I solator open at Bandamidi pally	Machanpally	I solator open at Bandamidi pally at 21:10 HRS.
2		Nagarkurnool	Manthathi	33KV	Nagarkurnool	23.15	00.00	00.45	E/L	Not Rectified	Manthathi	-
3		Maddur	Pallerla	33KV	Mahabubnagar	06.50	07.10	00.20	E/L	Insulator flash over near Maddur	Pallerla	Back Feeding Supply Taken From 132KV SS Kosgi at 7:10Hrs
1	MDK	Habsipur	Chittapur	33KV	Siddipet	18.10	18.45	00.35		B/D due to Insulater Failed	Chittapur	-
2		Tukkapur	Lingapur	33KV	Toopran	20.05	20.45	00.40		B/D due to Tree Branches Fallen on line at Venkatraopet	Lingapur	-
1	RR N	Medchal	Athiwelly	33KV	Medchal	09.20	10.22	01.02	BD	No Visible faults	Athiwelly	-

TSSPDCL - LMRC / Corporate office

Date: 22.06.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Rajapur	Mallepally	11KV	Jadcherla	10.00	13.00	03.00		11KV Jumper cut near Peddadagada	-
1	NLG	Kandagatla	Guttakinda	11KV	Suryapet	14.30	16.40	02.10	E/L	Insulator failed	-
2		Keethavari gudem	Rainigudam	11KV	Huzurnagar	05.30	08.00	02.30	EL	Due to 11Kv Jumper cut near Rainigudam Village	-
3		Mushampally	Muthyalammagudem	11KV	Nalgonda	00.00	06.00	06.00	E/L	11 KV Insulator Failes	-
4		Pagidimarri	Madanapuram	11KV	Nalgonda	07.00	09.00	02.00	E/L	11 KV Jumper Cut at SS-15	-
1	MDK	Cheryal	Kalivemula	11KV	Sangareddy	16.00	17.45	01.45		B/D Due to tree faleen on the line at Kashipur	-
2		Kowdipally	Yelmakanna	11KV	Medak	10.15	14.40	04.25		B/D Due to 11KV Conductor cut at Yelmakkanna village	-
3		Bujrampet	Bujrampet	11KV	Medak	02.00	07.30	05.30		B/D Due to Tree branches	-
4		Rajpet	Thimmapur	11KV	Medak	05.00	13.00	08.00		B/D Due to 11KV Line cut	-
5		Hathnoora	Nawabpet	11KV	Medak	07.00	14.00	07.00		B/D Due to 11KV Line cut at Nawabpet village	-
6		Kanukunta	Antharam	11KV	Medak	10.35	16.30	05.55		B/D Due to Strretlihg work	-
7		Kallakal	Muppireddypally SS	11KV	Toopran	17.05	18.05	01.00		B/D Due to 11KV Line cut	-
1	RR S	NPA	Hasan nagar	11KV	RJNR	06.48	07.58	01.10		Tree branchaces fallen on 11 KV line at Hasan nagar	-
1	RR N	Gachibowli	Mezzequity	11KV	Gachibowli	17.25	19.00	01.35	BD	11KV Pin Insulator Failed At Gowthami Society.	-
2		Gachibowli	Sriram Nagar	11KV	Gachibowli	17.50	19.00	01.10	BD	Tree Branches Fallen On The 11KV Line At Sriram Nagar 'A' Block.	-
3		Chandanagar	Madinaguda	11KV	Gachibowli	17.10	19.10	02.00	BD	Tree Branches Fallen On The 11KV Line Near RTC Colony At My Home Apts Side.	-
4		Chandanagar	Mythri Nagar	11KV	Gachibowli	17.15	19.10	01.55	BD	Tree Branches Fallen On The 11KV Line Near RTC Colony At My Home Apts Side.	-
5		IDPL	Moosapet	11KV	Gachibowli	17.20	18.20	01.00	BD	Due To Heavy Rain And Wind. No Visible Fault.	-
6		Chandanagar	Shankar Nagar	11KV	Kukatpally	17.05	18.15	01.10	BD	Inter Net Wire Fallon the 11kv line near Raghavendra Apt at Gayathrinagar	-
7		GP Pally	Nibeerwood	11KV	Medchal	06.30	07.40	01.10	BD	11KV Conductor Snapped at PN Prakash Rao Thota,GP Pally	-
8		Aliabad	Gubba	11KV	Medchal	18.40	19.20	00.40	BD	11KV Disc failed at near by Gubba	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	Cherlapally	Rampally	11KV	Habsiguda	17.45	18.35	00.50		Branches fallen near TEC Building	-
2		ABDULLAPURMET	SANGHI AGL	11KV	SAROORNAGAR	08.20	11.50	03.30	OL	11KV LINE PEROLLING NO FALT	-
3		RFC	ANAJ PER AGL	11KV	SAROORNAGAR	11.32	14.10	02.28	EL/OL	11KV OUT GOING SIDE JUMPER CUT AND 11KV INSULATOR FAIL AT RFC SS	-
4		Aushapur	Sandhupatlaguda	11KV	Habsiguda	19.20	21.10	01.50		Pin Insulator failed at Edulabad Village	-
1	HYD N	H.P.S	R.B.I Quarters	11KV	IV	01.08	03.24	02.16	EL	Cable fault	Arranged B/F on 11KV Begumpet Nala feeder
2		I.D.P.L		11KV	VI	17.20	18.45	01.25	EL,OL-Rph	Tree branches fallen on lines at Plot No.60	-----
3		Gunrock	Bowenpally	11KV	V	17.30	20.10	02.40	EL,OL-Bph	HT/LT Line snapped at Bowenpally Bus Stop	-----
4		Gymkhana	Vayu Sena	11KV	V	17.35	20.20	02.45	EL	HT Line snapped at Vayu Sena	-----
5		Yousufguda	Gayatri Hills	11KV	X	18.10	19.30	01.20	EL,OL-Rph	Tree branches fallen on lines at A.G Mother Home	-----
6		Nehru Nagar	J.B.S	11KV	V	18.20	19.58	01.38	EL,OL-Rph	No Visible Fault	-----
1	HYD S	Chanchalguda	Chowni	11KV	VIII	21.05	22.48	01.43	OL-R&Bph	UG Cable fault at Hakeem Cycle Taxi	Arranged B/F on 11KV Kurmaguda & 11KV Bada Bazar fdrs