

TSSPDCL - LMRC / Corporate office

Date: 01.05.17

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Mattampally	Bnl thanda	33KV	Huzurnagar	16:15	19:00	2:45	EL/OL	33KV Insulator failed at Beelya naik thanda vilage	Bnl thanda	No
2		Marriguda	Marriguda	33KV	Devarakonda	22.20	23.20	01.00		Jumper cut	Marriguda	No
1	RR E	Bandalguda	Nagole-I	33KV	Saroonagar	11:49	12:20	0:31		33KV Cable fault	Nagole-I	Alternate Supply arranged from 33KV Moosarambagh
2		Bandalguda	Nagole-II	33KV	Saroonagar	11.48	12.15	00.27		33KV Cable fault	Nagole-II	Alternate Supply arranged from 33KV Kothapet

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kosgi	Vittalapur	11KV	Mahabubnagar	06.00	09.45	03.45		11KV Conductor cut at Mukthipad (V)	No
2		Devarkadra	Lalkota	11KV	Mahabubnagar	06.00	11.30	05.30		11KV Conductor cut at Gopulapur (V)	No
3		Balanagar	Mothi ganpur	11KV	Jadcherla	12.00	14.00	02.00		11KV Line Phase to phase near SS	No
4		Avancha	Buddasamudram	11KV	Jadcherla	00.00	10.00	10.00		11KV disc failed near Buddasamudram	No
5		Avancha	Avancha	11KV	Jadcherla	0:00	10:00	10:00		11KV wire cut near Ippalapally road	No
6		Madharam	Madharam	11KV	Jadcherla	00.00	08.00	08.00		11KV Jumper cut near Chinnaipally	No
1	NLG	Nemmani	Pothinenipally	11KV	Nalgonda	13:00	16:30	3:30	O/L	11KV Line cut at Village out skirts	No
2		Keshrajupally	Mahilaprananam AGL	11KV	Nalgonda	14.40	17.00	02.20	E/L	11KV Jumper cut	No
3		Gollaguda	Hospital	11KV	Nalgonda	14.15	17.35	03.20	E/L	Poles damaged due to heavy gale and wind	No
4		Katangur	Duganelli	11KV	Suryapet	09.00	12.00	03.00	EL	Jumper cut	No
5		Ravulapally	Manapuram	11KV	Suryapet	14.00	16.00	02.00	EL	Pin insulator failed	No
6		Kondamadugu	Nemaragomula	11KV	Bhongir	02.00	05.00	03.00	EL	11KV Line snapped at Nemaragomula	No
7		Chandupatla	Veeravally	11KV	Bhongir	07.00	09.45	02.45	EL	Tree branches fallen on the line	No
8		Rajapet	Pamukunta	11KV	Bhongir	08.40	11.00	02.20	EL	11Kv Line snapped at Puttagudem	No
9		Marriguda	Vattiipally	11KV	Devarakonda	09.00	12.30	03.30	E/L	Insulator failed	No
10		Mukundapuram	Mundapuram	11KV	Huzurnagar	07.00	09.15	02.15	EL	11 KV Line snapped at Mukundapuram village	No
11		Gaddipally	Kutubshapuram	11KV	Huzurnagar	06.00	09.30	03.30	EL	11 KV Line snapped at Kutubshapuram village	No
12		Mattapally	Sulthanpur thanda	11KV	Huzurnagar	13.30	15.45	02.15	EL	11 KV Line snapped at Sulthanpur thanda village	No
13		Repala	Repala	11KV	Huzurnagar	14.30	16.10	01.40	EL	11 kv line snapped at Repala village	No
14		BNL THANDA	Pathathanda	11KV	Huzurnagar	13.15	17.00	03.15	EL	11 kv line snapped at Pathathanda village	No
15		Ponugodu	Ponugodu	11KV	Huzurnagar	09.30	10.30	01.00	EL	11 kv LT Touched at ponugodu village	No
16		Janpahad	Ravipahad	11KV	Huzurnagar	15:30	18:00	2:30	EL	11 KV Line snapped at Ravipahad village	No
1	MDK	Amsanpaly	Kongode	11KV	Medak	5:00	6:00	1:00		Tree branch fallen on the 11KV conductor	No
1	RR S	Marpally	Patlur	11KV	Vikarabad	6:45	7:47	1:02	EL	Insulator failed at Mogiligundla village	No
1	RR N	Kandlakoya	Kandlakoya	11KV	Medchal	21:05	22:30	1:25		11KV Pole damaged by Lorry at Sutariguda Petrol Pump	No
2		Gachibowli	Nalagandla	11KV	Gachibowli	20.55	22.35	01.40		Tree branches fallen on the 11KV Line At Gulmohar Park.	No
1	RR E	Rajeev Swagruha	Jaipuri Colony	11KV	Saroor Nagar	19:46	20:50	1:04		No visible fault	No
2		VP Nagar	VV Puram	11KV	Sainikpuri	02.34	03.29	00.55		11KV Cable failed at Opposite Sub Station Gate	No
1	HYD N	E.S.I	B.K Guda	11KV	Erragadda	00.20	02.37	02.17	All Indication	11KV AB Cable fault at Prana International Society	No
1	HYD C	Nampally	FAPCCI	11KV	Mehdipatnam	19.31	21.20	01.49	EL,OL	Tree branches fallen on 11KV Lines at Criminal Court Masjid	No

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	77	404		2		2		2			
6	RR(E)	38	347	2	2	2	2	2	2			
7	Hyd	184	993		2		2		2			
	<b>Total</b>	<b>497</b>	<b>2892</b>	<b>2</b>	<b>6</b>	<b>2</b>	<b>6</b>	<b>2</b>	<b>6</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	108	969		6		6		6			
2	NLG	150	948	2	16	2	16	2	16			
3	MDK	87	828		1		1		1			
4	RR(S)	29	322		1		1		1			
5	RR(N)	8	48									
6	RR(E)	18	80									
	<b>Total</b>	<b>400</b>	<b>3195</b>	<b>2</b>	<b>24</b>	<b>2</b>	<b>24</b>	<b>2</b>	<b>24</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>897</b>	<b>6087</b>	<b>4</b>	<b>30</b>	<b>4</b>	<b>30</b>	<b>4</b>	<b>30</b>	<b>0</b>	<b>0</b>	