

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		1		1		1			
5	RR(N)	77	404		1		1		1			
6	RR(E)	38	347		1		1		1			
7	Hyd	184	993		2		2		2			
	Total	497	2892	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	108	969	7	1	7	1	7	1			
2	NLG	150	948		1		1		1			
3	MDK	87	828	2		2		2				
4	RR(S)	29	322									
5	RR(N)	8	48									
6	RR(E)	18	80									
	Total	400	3195	9	2	9	2	9	2	0	0	
	Grand Total	897	6087	9	7	9	7	9	7	0	0	

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Kodoor	33KV	Mahabubnagar	18.05	21.30	03.25	E/L	Heavy Gail and Wind and Isolator Open at Machanpallythat is parpally line	Kodoor	Isolator Open at Machanpallythat is parpally line
2		Palakonda	Kodur	33KV	Mahabubnagar	21.40	22.25	00.45	E/L	Insultor failed and trees follen on the line near Petrol Bunk	Kodur	-
3		Makthal	Narwa	33KV	Mahabubnagar	18.50	21.40	02.50	E/L	clamp bolt damged and replaced 132KV Makthal SS	Narwa	-
4		Wanaparthi	Revally	33KV	Wanaparthi	20.20	21.30	01.10	E/L	Heavy Gail and Wind & Rain Supply stude OK	Revally	Alternate Supply Arranged from 33KV Peddakothapally at 21:30Hrs
5		Ghanapur	Solipur	33KV	Wanaparthi	23.20	00.00	00.40	E/L	No visible fault	Solipur	-
6		Gadwal	Nandine	33KV	Gadwal	19.20	23.30	04.10	E/L	AB Swith open at Peddapad SS due to Heavy Gail and Wind & Rain Supply stude OK	Nandine	-
7		Gadwal	Alwalpad	33KV	Gadwal	22.45	00.00	01.15	E/L	AB Swith Open due to Heavy Gail and Wind & Rain Supply stude OK	Alwalpad	-
1	MDK	Siddipet	Kammarlapally	33KV	Siddipet	07.45	09.05	01.20		B/D due to Tree Branches fall on the line	Kammarlapally	-
2		Habsipur	Dubbak	33KV	Siddipet	16.10	17.10	01.00		B/D due to Jumper cut	Dubbak	-

TSSPDCL - LMRC / Corporate office

Date: 06.05.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Dindi Chinthapally	Dindi Chinthapally	11KV	Jadcherla	13.00	15.00	02.00		11Kv Wire Cut Near Vishnu Varthan Bavi Side.	-
1	NLG	R.C Puram	R.C Puram	11KV	Suryapet	05.00	07.30	02.30	E/L	Grass Fallen	-
1	RR S	Rajendranagar	Rajendranagar	11KV	Rajendranagar	22.52	00.45	01.53		33 KV REV Line Fallen on 11 KV Rajendranagar Line at Budvel	-
1	RR N	Jeedimetla-I	APIIC Colony	11KV	Kukatpally	06.32	08.40	02.08	BD	11kv Ab Cable Failure near Lines club school at APIIC Colony	-
1	RR E	Ramoji Filim City	Anjapur	11KV	SRNR	20.40	22.50	02.10		DTR Copper Patty cut at Anjapur (V)	-
1	HYD N	Jana Priya	I.O.L	11KV	X	14.58	16.45	01.47	EL,OL-Bph	AB Cable fault at Mothi Nagar	-
1	HYD S	Kandikalgate	Gazimillath Colony	11KV	III	08.00	09.35	01.35	EL,OL	RMU Lugs B/o at Goyal Oil Mill	-